



Republic of Namibia
Zambezi Regional Council
DIRECTORATE OF EDUCATION, ARTS AND CULTURE



Tel: +264-66-261908
Fax: +264-66-252941

Ngoma/ Hospital Road
Govt Building/ ZRC Office Park

Private Bag 5002
Katima Mulilo

Request for Quotations
For Non-Consultancy Services

PROVISION FOR REPAIR(S) AND SERVICING OF GRN TRACTORS AND TRAILERS, IMPLEMENTS, VEHICLE MOUNTED SPRAYERS AND MIST BLOWERS FOR ZAMBEZI DAPEES.

Procurement Reference No: NCS/RB/ZRC-DAPEES 05/2026/2027

BIDDER

ADDRESS

TEL

FAX/EMAIL

Total price

Bid Amount in words.....

.....

.....

DOCUMENTS MUST BE DELIVERED BEFORE 10H00 ON THE CLOSING DATE TO:

The Secretary:
Zambezi Regional Council Procurement Committee
Ngoma Road
Private Bag 5002
Katima Mulilo
Namibia





**REPUBLIC OF NAMIBIA
ZAMBEZI REGIONAL COUNCIL**



LETTER OF INVITATION

NCS/RB/ZRC-DAPEES 05/2026/2027

Dear Sir/Madam,

INVITATION FOR BIDS: PROCUREMENT OF SERVICE PROVIDERS ON DRYLAND CROP PRODUCTION PROGRAMME (DCPP) AND CEREAL VALUE CHAIN (CVC) FOR REPAIR(S) AND SERVICING OF GRN TRACTORS AND TRAILERS, IMPLEMENTS AND OTHER MACHINERIES (VEHICLE MOUNTED MACHINES AND MIST BLOWERS) FOR ZAMBEZI DAPEES.

The Zambezi Regional Council invites you to submit your best bid for the items described in detail hereunder.

Any resulting contract shall be subject to the terms and conditions referred to in the document.

Queries, if any, should be addressed to **Mr. Abraham Shikoyeni, telephone no: 066-261, Head: Procurement Management Unit, Zambezi Regional Council, Private Bag 5002, Katima Mulilo.**

Please prepare and submit your quotation in accordance with the instructions given or inform the undersigned if you will not be submitting a bid.

Yours faithfully,

**MR. ABRAHAM SHIKOYENI
HEAD: PROCUREMENT MANAGEMENT UNIT**

DATE.....



SECTION I: INSTRUCTIONS TO BIDDERS

1. Rights of Public Entity

The *Zambezi Regional Council* reserves the right:

- (a) to split the contract as per the lowest evaluated cost per lot; and
- (b) to accept or reject any quotation or to cancel the quotation process and reject all quotations at any time prior to contract award.

2. Eligibility Criteria

To be eligible to participate in this Quotation exercise, you should:

- (a) have a **certified copy** of company founding statement
- (b) have a **valid certified copy** of Good Standing Certificate (BIPA);
- (c) have an **original** valid Good Standing Tax Certificate (NamRA);
- (d) have an **original** valid Good Standing Social Security Certificate;
- (e) have a **valid certified copy** of Affirmative Action Compliance Certificate, proof from Employment Equity Commissioner that bidder is not a relevant employer, or exemption issued in terms of Section 42 of the Affirmative Action Act, 1998;
- (f) Valid certified copy of owner/owner's identification documents

3. Qualification and Additional Requirements

- 1 Minimum 4 qualified mechanics and minimum 6 assistants (curriculum vitae should be attached)
- 2 Minimum N3 in Diesel Mechanics (certified copy of qualifications should be attached)
- 3 Minimum 3 years of experience in repairing and servicing of tractors and trailers, implements, vehicle mounted sprayers and mist blowers valid proof of previous work done (attach reference letters) certificate of service.
- 4 Appropriate workshop facilities: Proof of ownership or lease agreement. Inspection to be done by public entity before appointment.
- 5 Willingness to work during rainy season: Attach a letter indicating the bidder's commitment to work during the festive season and attend to call-outs within and outside Katima Mulilo.
- 6 The bidder's workshop should be at least within Katima Mulilo where repair(s) and servicing will be rendered.

4. Machinery and tools capacity: Minimum (Workshop(s) to be inspected by Public Entity)

- 1. Portable Compressor x 3
- 2. Heavy duty Compressor (maximum 150kg) x 1
- 3. Chain Block and Tackle x 1
- 4. Welding Machine x 2
- 5. Tool box per Mechanic x 1
- 6. Portable Generating Set x 1

7. 4x4 Bakkie x 2
8. Machinery for tyre repairs such as knocker beater, tyre levers, wheel balancing machine and tyre remover x 1

5. Specific Regions to render servicing of tractors and implements: Restricted to **Zambezi Region Only**

6. Contract Period for Services

The contract shall be on fixed rate for a period of **three (3) years** after the closure.

7. Documents to be submitted

Bidders shall submit along with their quotation(s) documents giving company's profile, past experience and evidence of similar services provided with customers' reference details.

8. Sealing and Marking of Bids.

Quotation(s) should be sealed in a single envelope, clearly marked with the **Procurement Reference Number**, addressed to **Zambezi Regional Council Procurement Committee** with the Bidder's name and contact information at the back of the envelope.

9. Submission of Bids

Bids should be deposited in the Quotation/Bid Box located at ***Zambezi Regional Council, Ngoma Road, Katima Mulilo, not later 12 August 2026 at 10H00***, Quotations by post or hand delivered should reach *Zambezi Regional Council* by the same date and time at latest. Late bids will be rejected.

Bids received by e-mail will not be considered.

10. Opening of Bids

Bids will be opened internally by the Public Entity at **Zambezi Regional Council on 12 August 2026 at 10H00**. The bidders or their representatives may attend the Bid Opening if they choose to do so.

11. Evaluation of Bids

The Public Entity shall have the right to request for clarifications in writing during evaluation. Offers that are substantially responsive shall be compared on the basis of evaluated cost, subject to Margin of Preference where applicable, to determine the lowest evaluated bid.

12. Scope of Services and Performance Standards

The Scope of Services, Specifications and Performance standards detailed in Sections IV are to be complied with.

12.1. List out or Attach Scope of service to be carried out

#Stripe and quote

#Call out service, repair and breakdown

#Schedule maintenance service

#Supply and replacement of parts, componets and accessories

#

(NB. Insert scope, services required, repairs, parts, componets, etc)

BID SECURING DECLARATION
(Section 45 of Act)
(Regulation 37(1)(b) and 37(5))

Date: [Day|month|year].....

Procurement Ref No.: NCS/RB/DAPEES05/2026/2027

To: Zambezi Regional Council
Directorate of Agricultural Production, Engineering and Extension Services
Katima Mulilo

I/We* understand that in terms of section 45 of the Act a public entity must include in the bidding document the requirement for a declaration as an alternative form of bid security.

I/We* accept that under section 45 of the Act, I/we* may be suspended or disqualified in the event of

- (a) a modification or withdrawal of a bid after the deadline for submission of bids during the period of validity;**
- (b) refusal by a bidder to accept a correction of an error appearing on the face of a bid;**
- (c) failure to sign a procurement contract in accordance with the terms and conditions set forth in the bidding document, should I/We* be successful bidder; or**
- (d) failure to provide security for the performance of the procurement contract if required to do so by the bidding document.**

I/We* understand this bid securing declaration ceases to be valid if I am/We are* not the successful Bidder

Signed:

Capacity
of:.....
.....

Name:

Duly authorized to sign the bid for and on behalf of:
.....

Dated on _____ day of _____

Corporate Seal (where appropriate)

[Note*: In case of a joint venture, the bid securing declaration must be in the name of all partners to the joint venture that submits the bid.]

2. PROCURMENT DETAILS

Procurement Reference No:

Procurement Description:

.....

.....

Anticipated Contract Duration:

Location where work will be done, good/service will be delivered

.....

3. UNDERTAKING

I..... [insert full name] owner/ representative

Of [insert full name of
company]

hereby undertake in writing that my company will at all times comply fully with the relevant provisions of the Labour Act and the Terms and Conditions of Collative Agreement as applicable

I am fully aware that failure to abide to such shall lead to action as stipulated in section 138 of labour Act, 2007, which include but not limited to the cancellation of the contract/license/grant/permit or concession

Signature:.....

Date:

Seal:

Please take note:

1. A labour inspector may conduct unannounced inspections to assess the level of compliance
2. This undertaking must be displayed at the workplace where it will be readily accessible and visible by the employees rendering service(s) in relations to the goods and services being produced under this contract

SPECIFICATIONS

SECTION V: SPECIFICATIONS AND COMPLIANCE SHEET

Procurement Reference Number: NCS/RB/ZRC-DAPEES 05/2026/27

A. *[Bidders should complete columns C and D with the specification and performance of the Works offered. Also state “comply” or “not comply” and give details of any non-compliance/deviation to the specification required. Attach detailed technical literature if required. Authorize the specification offered in the signature block below]*

B.

Item No	Specifications and Performance Required	Compliance of Specifications and Performance Offered	Details of Non-Compliance/ Deviation (if applicable)
<i>A*</i>	<i>B*</i>	<i>C</i>	<i>D</i>
1	Markup % on spare parts should not exceed 15 % a) To provide spare parts continuously when called for breakdown, not modifying b) To attend to call –outs timely.		
2	Strip and quote (N\$/Hour) a) To quote and supply the right and genuine spare parts		
3	Human Capacity a) Minimum 4 qualified mechanic and minimum 6 assistants (Attach Curriculum Vitae)		
4	Qualifications: a) Minimum N3 in Diesel mechanics (Attach Certified copies of qualifications)		

Item No	Specifications and Performance Required	Compliance of Specifications and Performance Offered	Details of Non-Compliance/ Deviation (if applicable)
<i>A*</i>	<i>B*</i>	<i>C</i>	<i>D</i>
5	Machinery and Tools capacity Minimum a) Attach list of machineries and Tools (Workshop to be inspected) 1. Portable Compressor x 3 2. Heavy duty Compressor (maximum 150kg) x 1 3. Chain Block and Tackle x 1 4. Welding Machine x 2 5. Tool box per Mechanic x 1 6. Portable Generating Set x 1 7. 4x4 Bakkie x 2 8. Machinery for tyre repairs such as knocker beater, tyre levers, wheel balancing machine and tyre remover x 1		
6	Relevant Work History a) Minimum 3 years of experience in repairing and serving of tractors and trailers, implements, vehicle mounted sprayers and mist blowers b) Valid proof Previous work done(attach reference letter)		
7	Appropriate workshop facility a) Proof of Ownership / Lease agreement		
8	Willing to work during festive season and attend to call outs a) Attach a letter indicating the bidder's commitment to work during festive season		
9	Proof of Financial capacity a) The bidder is only paid upon verification that the procuring entity is satisfied with the service rendered, hence the bidder is required to provide proof of financial capacity to service and repair tractors and trailers, implements, vehicle mounted machines and mist blowers in advance before payments are made.		
10	Servicing of GRN tractors and trailers, implements, vehicle mounted sprayers and mist blowers to be rendered in		

SECTION VI: EVALUATION CRITERIA

Table 1: Mandatory, Qualification and Additional Technical Requirements

Document Description	Yes/No
1. A certified copy of the valid Company Registration Certificate or Registration of Defensive Name if applicable issued by the Ministry of Industrialization and Trade or BIPA.	
2. An original or certified copy of a valid Good Standing Tax Certificate from the Receiver of Revenue (NAMRA).	
3. An original or certified copy of a valid Good Standing Certificate from the Social Security Commission.	
4. A certified copy of a valid Affirmative Action Compliance Certificate or in its absence, proof from the Employment Equity Commissioner that the Bidder is not a relevant employer, or exemption issued in terms of Section 42 of the Affirmative Action Act, 1998;	
5. A duly completed and signed Bid Securing Declaration form.	
6. A duly signed and completed Bid submission form	
7. Document completed in black ink	
8. No Eraser fluids used	
9. Each page of the bid document should be initialed and the bid document should be fully completed with accurate information at relevant spaces provided.	
10. A Certified copy of identification documents (IDs) of the owner(s) of the company or shareholders or members of the trustee	
11. A minimum of 4 qualified mechanics and 6 assistants	
12. Certified copy of qualifications that are a minimum N3 in Diesel Mechanics	
13. A minimum of 3 years of experience in repairing and servicing of tractors and trailers, implements, vehicle mounted sprayers and mist blowers with valid proof of previous work done (to be attached) certificate of services	
14. Proof of ownership / lease agreement	
15. A letter indicating the bidder's commitment to work during rainy season and call outs.	

Phase 2: Technical evaluation

Bidders who did not meet the technical evaluation cannot proceed to the next step.

Phase 3: Financial Evaluation


The prices shall be evaluated on the lowest substantive economically responsive bidder (s)

SCHEDULE 3

QUOTATION CHECKLIST SCHEDULE

Procurement Reference No.: **NCS/RB/ZRC-DAPEES 05/2026/2027**

Description	Attached (please tick if submitted and cross if not)
Quotation Letter	
Written undertaking in terms section 138 of the Labour Act, 2015 and Section 50(2) of the Public Act, 2015	
Performance Compliance Sheet	
Bid Security (if applicable)	
Documents evidencing eligibility (Mandatory documents)	
Company profile, past experience and references where similar services have been provided	



REPUBLIC OF NAMIBIA
ZAMBEZI REGIONAL COUNCIL



Tel: +264 66 261700

Fax: +264 66 252650

Ngoma Street
Govt. Building

Private Bag 5002

Katima Mulilo

Enquiries: Mr. R. Maswabi/0814152357

30 June 2026

THE ACTING CHIEF REGIONAL OFFICER

ZAMBEZI REGIONAL COUNCIL

MINISTRY OF AGRICULTURE, FISHERIES, WATER AND LAND REFORM

DIRECTORATE OF AGRICULTURAL PRODUCTION, EXTENSION AND ENGINEERING SERVICES, ZAMBEZI REGION.

Re: Defects on GRN Tractors and trailers, implements, vehicle mounted sprayers, walking tractors, vehicle mounted sprayers and mist blowers which need repairs for the 2026/27, 2027/28 and 2028/29 cropping season.

- Kindly assist with quotations for the under- listed GRN tractors and trailers, implements, walking tractors, vehicle mounted sprayers and mist blowers as per different service required.

a) GRN tractor and trailer repair and spare parts for 2026/27, 2027/28 and 2028/29

GRN No./ ID of Tractor Make Chassis /Engine No.	Service Last Service (Hours)	Additional repairs required.	Tyres	ADC/ Location
1...GRN18937 (MF460).	Service required	• Check and repair oil leakage on the left front hub and 4x4. • Check and repair fuel tank crack on top of the tank, • All lights not working • Top oil leakages on the changing gear levers,	Replacement of front and rear tyres.	Katima Mulilo AMTA Silos
2. GRN18938 (MF460).	Service required	• Check and repair front axle 4x4 and indicators not working and control arms not dropping the plough.	Replace front tyre	Katima Mulilo AMTA Silos
3. GRN 18940 (MF 460).	Service required	• Check and repair 4x4 not working, • Leakages on the front hub • Damaged bearing on the front right hub and cannot lift heavy disc harrow.		Katima Mulilo AMTA Silos
4. GRN18941 (MF460).	Service required	• Check and repair electrical system, light not working properly • Not pulling check the hydraulic filter or clutch plate.	Replace battery.	Katima Mulilo AMTA Silos

5. GRN18751 (MF455).	Service required	• Check and repair diesel pump not working • Leakages on the front axle, bred air lock, oil leakages on the rear axle, • Brake not working • Hand throttle • Not working grease all nipples and change nipples.	Replace battery.	Katima Mulilo AMTA Silos
6. GRN18753 (MF455).	Service required	• Check and repair leakages on the right and left hubs wheels • Check and repair brake system • Reduces the speed when driving and check the electrical system • Lights not working. • Check and repair oil leakages on top of the brake kit.		Katima Mulilo AMTA Silos
7. GRN18711 Agrale	Service required		Replace front tyre.	Katima Mulilo AMTA Silos
8. GRN19906 (John Deere).	Service required			Katima Mulilo AMTA Silos
9. GRN19920 (John Deere)	Service required	Replace fuel tank.		Katima Mulilo AMTA Silos
10. N83708W (John Deere)	Service required			Katima Mulilo AMTA

Deere).		• Check and repair 4x4 not working, electrical • System lights not working) • It burns fuses, when switching off the key • Hotter not working.		Silos
---------	--	---	--	-------

11. N140-293W (John Deere 5082E).	Service required	• Check and clean the fuel tank • Check and replace the bolts holding the lifting arm left are broken and threats are finished.	Replacement two front tyres.	Katima Mulilo AMTA Silos
12. N64806W (John Deere 5082E).	Service required	• Check and replace the tractor not pulling or moving when it engaged it takes back to neutral • Adjustor army broken • Dirty fuel tank • Check electrical system lights not working.	Replace battery. Replace front tyre.	Katima Mulilo AMTA Silos
13. N38107W (John Deere 5082E).	Service required	Check and clean the fuel tank	Replace front tyres.	Katima Mulilo AMTA Silos
14. N219-373W (John Deere 6095B).	Service required	• Check and clean the fuel tank • Hour meter not working and lights not working.	Replace battery.	Katima Mulilo AMTA Silos

15. N 140-283w (John Deere 5082E).	Service required	• Check and clean the fuel tank • Failing to pull, leakages on the arm • Handbrake not working.		Katima Mulilo AMTA Silos
16.N219400W (John Deere 6095B)	Service required	• Check and clean the fuel tank • Electrical system lights not working		Katima Mulilo AMTA Silos
17. N 87268W (John Deere 5082E).	Service required	Check and clean the fuel tank		Katima Mulilo AMTA Silos
18+.N 219418W (John Deere 6095B).	Service required	Check and clean the fuel tank Lights not working		Katima Mulilo AMTA Silos
19. N219-403W (John Deere 6095).	Service required	Check and clean the fuel tank, Hour meter not working, electrical system light not working and it puts itself to neutral while driving.		Katima Mulilo AMTA Silos
20. N63029W (John Deere 5082E).	Service required	Tractor not engaging in gears. Check and clean the fuel tank		Katima Mulilo AMTA Silos
21. N210-395W John Deere 6095B).	Service required	Check and clean the fuel tank and repair the left rear rim.	Replace two front tyres.	Katima Mulilo AMTA Silos
22. Changli 1054, YT22258090	Service required	• Replacement of broken (mould board plough, Hydraulics pipe. • Routine service needed; • Front Trailer bearing worn-out need replacement		Bukalo ADC
23. Changli 1104 YT22258089	Last service was Below 50 Hours	• Replacement of broken (mould board plough, Hydraulics pipe.		Bukalo ADC

	service			
24. Changli 1104 YT22258100	Last serviced At 50 Hours	• Routine service needed; • Leaking of oil (from the exhaust pipe); Tractor not pulling; • Replacement of broken (mould board plough.) • Routine service needed.		Chinchimani ADC
25. Changli 1054 YT22258706	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed; • Tractor cannot start need attention and full mechanical diagnosis fault check.		Chinchimani ADC
26. Changli 1104 YT22258093	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed.		Sibbinda ADC
27. Changli 1054 YT22258092	Last serviced At 50 Hours	• Replacement of broken (mould board plough, Hydraulics pipe) • Routine service needed; • Clutch needs adjustment or service and full fault check.		Sibbinda ADC
28. Changli 1104 YT22258098	At 5 Last serviced At 50 Hours 0 Hours	• Replacement of broken (mould board plough.) • Routine service needed. • Replacement cap (tractor selter). • Replacement of front wheel bearing on the trailer.		Ngoma ADC
29. Changli 1104	Last serviced At 50	• Replacement of broken		Masokotwani ADC

	Hours	(mould board plough) • Routine service needed. • Battery replacement. • Replacement of broken arm.		
30. Changli 1054	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed; • Clutch needs adjustment or service & full fault check. • Replacement of Front wheel bearings. • Missing cap on oil tank.		Masokotwani ADC
31. Changli 1104	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed. • Replacement o control Arms		Katima ADC
32. Changli 1104	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed; • Replacement of Front wheel bearings on the trailer.		Linyanti ADC
33. Changli 1054 YT22258096	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed; • Leaking of oil power steering pump.		Sangwali ADC
34. Changli 1104 YT22258097	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed; • Clutch needs adjustment or service		Kongola ADC
35. Changli 1054	Last serviced At 50	• Replacement of broken		Sachona ADC

YT22258099	Hours	(mould board plough,) • Routine service needed;		
36. Changli 1054 YT22257705	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed. • Control arms to be rearranged not fitted to standards.		Kasheshe ADC
37. Changli 1104 YT22258101	Last serviced At 50 Hours	• Replacement of broken (mould board plough,) • Routine service needed.		Kabbe ADC
38. ACE A90TCTQBC0017365	Last serviced At 50 Hours	• Clutch needs adjustment or service; • Replacement of broken or missing parts (Disc, Bearing, Shafts; u bolts). • Routine service needed and broken light.		Bukalo ADC
39. ACE A90TCTQBC0017368	Last serviced At 50 Hours	• Replacement of broken or missing parts (Disc, Bearing, Shafts; u bolts). • Provide the replaceable shafts U-bolts and greasing gun.		Bukalo ADC
40. ACE A90TCTQBC0017369	Last serviced At 50 Hours	• Replacement of broken or missing parts (Disc, Bearing, Shafts; u Bolts) • Provide the replaceable shafts U-bolts and greasing gun		Chinchimani ADC
41. ACE A A90TCTQB0017371	Last serviced At 50 Hours	• Replacement of broken or missing parts (Disc, Bearing, mould board plough, Shafts U-bolts) Routine service needed • Provide the replaceable		Sibbinda ADC

			shafts U-bolts and greasing gun.		
42. ACE A90TCTQB0017366	Last serviced At 50 Hours		• Replacement of broken or missing parts (Disc, Bearing, mould board plough Shafts u-bolts & nates); • Provide the replaceable shafts U-bolts and greasing gun.		Ngoma ADC
43. ACE A90TCTQB0017372	Last serviced at 250 hours		• Replacement of broken or missing parts (Disc, Bearing, mould board plough Shafts u-bolts & nates); • Provide the replaceable shafts U-bolts and greasing gun.		Masokotwani ADC
44. ACE A90TCTQB0017369	Last serviced at 250 hours		• Replacement of broken or missing parts (Disc, Bearing, Shafts). • Clutch needs adjustment or service tractor not pulling. • Provide the replaceable shafts U-bolts and greasing gun.		Katima ADC
45. ACE A90TCTQB0017370	Last serviced at 250 hours		• Replacement of broken or missing parts (Disc, Bearing, mould board plough Shafts u-bolts & nates). • Provide the replaceable shafts U-bolts and greasing gun.		Linyanti ADC
46. ACE A90TCTQB0017367	Last serviced at 250 hours		• Replacement of broken or missing parts (Disc, Bearing, Mould board plough Shafts u-bolts & nates) gear lever broken. • Provide the replaceable shafts U-bolts and greasing gun.		Sangwali ADC

47. ACE A90TCTQB0017373	At 2 Last serviced at 250 hours 50 hours	• Replacement of broken or missing parts (Disc, Bearing, Shafts); • Provide the replaceable shafts U-bolts and greasing gun.		Kongola ADC
48. ACE A90TCTQB0017386	At 25 Last serviced at 250 hours 0 hours	• Replacement of broken or missing parts (Disc, Bearing, mould board plough Shafts u- bolts & nates). • Provide the replaceable shafts U-bolts and greasing gun.		Sachona ADC
49. ACE A90TCTQB0017376	Last serviced at 250 hours	• Replacement of broken or missing parts (Disc, Bearing, Mould board plough Shafts u- bolts & nates). • Provide the replaceable shafts U-bolts and greasing gun.		Kasheshe ADC
50. ACE A90TCTQB0017384	Last serviced at 250 hours	• Replacement of broken or missing parts (Disc, Bearing, Shafts); • Clutch needs adjustment or service; tractor not pulling. • Provide the replaceable shafts U-bolts and greasing gun.		Kabbe ADC

b) GRN Implement repair and spare parts for 2026/27, 2027/28 and 2028/29

Implement Types.	Serial numbers.	Spare parts needed.	ADC/Location
1. Baldan mould board ploughs x13.	608542084002; 608542086002; 608542087001; 608542087002; 608542088001; 608542088002; 608960002008; 609732023005; 608973203009; 609732023008; 609732003002; 609732023010.	*Supply 25 x Frogs. *Supply 25 x Frog arms. *Supply 25 x Shears. *Supply 15 landsides. *Supply 250 x Shear bolts, nuts & washers. *Supply 20 x 6m x 12mm round bars. *Check & repair 13 x mouldboard ploughs.	Katima Mulilo AMTA Silos
2. BPI mould board ploughs x 4.	SN6284; SN6381;	Supply 15 x shears. *Supply 10 x landsides. *Supply 15 x frog arms. *Supply 8 x frogs. *Supply 16 x Hitch pins. *Supply 200 x Shear bolts; nuts & washers. *Supply 10 x 6m x 8mm round bars. *Repair 4 x mouldboard ploughs.	Katima Mulilo AMTA Silos
3. Baldan disc harrows x 9.	608542027001; 608542041001; 608542070001; 608542037001; 608542079001; 608960001013; 609673001002	*Supply 25 x Discs shafts/excel with nuts. *Supply 12 x spacers. *Supply 15 x Bearings. *Supply 50 x Bearing bolts & nuts. 1 disc harrow still at Bomac	Katima Mulilo AMTA Silos
4. John Deere disc harrows x 4.	IP00660XLEN015530; IP00660XCEN015538; IP00660XPEN015535; IP00660XLEN015544; IP00660XJEN015537.	Supply X 8 disc shafts with bolts & nuts. *Supply 5 x U bolts & nuts.	Katima Mulilo AMTA Silos
5. Jumil planters-hitched x 9.	18853-E; 18877-E; 18871-E; 18887-E; 18867-E; 18886-E; 18876-E; 18854-E; 18888-E; 18872-E; 18868-E; 25362-E.	*Supply 15 x seed boxes. *Supply 15 x fertilizer boxes. *Supply 24 x fertilizer feeder pipes. *Supply 20 x rear rubber wheels. *Supply 12 x fertilizer control units. *Supply 12 x seed control units. *Supply 20 x seed covering side wheels. *Supply 30 x chain tension springs. *Supply 30 x feeder pipe clumps. *Supply 100 x bin screws with	Katima Mulilo AMTA Silos

			nuts. *Supply 50 x fert. Unit control bolts & nuts. *Repair 12 x jumil planters.	
6. BPI planters-trailed x 5.	9008; 9011; 9012; 9014; 9021; 9029; 9038.		*Supply 4 x tyres & tubes size 7.60-15 SL. *Check and repair 7 x BPI planters starting from hitch points; hydraulic pipes; fertilizer boxes assembly; seed boxes assembly; wheel assembly; etc.	Katima Mulilo AMTA Silos
7. John Deere planters 1010 x 5	IP01010XAEA004591; IP01010XVEA004587; IP01010XTEA004579; IP01010XJEA004571; IP01010XTEA004601.		*Check & repair 1 x planter. *Supply 10 x size 15 gears/sprockets. *Supply 6 x feeder pipes. *Supply 6 x feeder pipe clumps. *Supply 3 x tyres & tubes size 5.90-15 SL. 1x planter still at Bomac garage.	Katima Mulilo AMTA Silos
8. Riper-BPI 2 tines x 8.	3183; 3184; 3186; 3262; 3279; 3286; 3270.		*Supply 100 x safety bolts. *Supply 20 x wings.	Katima Mulilo AMTA Silos
9. Ripper-Baufi x 6.			*Supply 50 safety bolts and nuts.	Katima Mulilo AMTA Silos
10. Ripper V-John Deere x 5.	IP00913XEED013125; IP00913XHBE013124; IP00913XTED013127; IP00913XCED013126; IP00913XTED013032.		*1 x disc harrow still at Bomac garage. *Supply 4 x shafts. *Supply 12 x spacers. Supply 4 x U-bolts.	Katima Mulilo AMTA Silos
11. Trailers-4wheels x 7.	GRN 18169; GRN 18171; GRN 19120; GRN 19121; GRN 19145; SR NO.WHK 100722091034; SR NO.WHK 100722091037.		*Supply 14 x tyres and tubes sizes	Katima Mulilo AMTA Silos

GRN Distributed List for Implements and their Condition

No	ADCs	No Tipper Trailers	Condition & Remarks	No. Mould Board plough	Condition & remarks	No. offset Disc Harrow	Condition & remark	No. planter/Drill	Condition & remarks	No. Ripper
12	Chinchimani	2	Good replacement of bearing for Changli Trailers.	3	All need repair/ replacement	3	Replacement of bearings and U-bolts	3	The Ace planter is good and usable; Changli very long can't be used due to road access.	3
13	Bukalo	3	Good replacement of Bearing for Changli trailers.	4	All need repair/ replacement	4	Replacement of bearings and U-bolts	4	The Ace planter is good and usable; Changli very long can't be used due to road access.	4
14	Sibbinda	2	good	3	All need repair/ replacement	3	Replacement of bearings and U-bolts	3	The Ace planter is good and usable; Changli very long can't be used due to road access.	3
15	Katima	2	Ace trailer	2	All need	2	Replacement	2	The Ace	2

				damaged by tree Changli trailer Bearing Replacement			repair/ replacement		of bearings and U-bolts		planter is good and usable; Changli very long can't be used due to road access.	
16	Ngoma	2	Good	Changli Trailer bearing replacement	2	All need repair/ replacement	2	Replacement of bearings and U-bolts	2	The Ace planter is good and usable; Changli very long can't be used due to road access.	2	
17	Kongola	2	Good		2	All need repair/ replacement	2	Replacement of bearings and U-bolts	2	The Ace planter is good and usable; Changli very long can't be used due to road access.	2	
18	Sangwali	2	Good		2	All need repair/ replacement	2	Replacement of bearings and U-bolts	2	The Ace planter is good and usable; Changli very long can't be	2	

19	Linyanti	2		Good Changli Trailer Bering replacement	2		All need repair/ replacement	2	Replacement of bearings and U-bolts	2		used due to road access.	2	
20	Dudukabe	2		AceTrailer shaft bent need Attention, Changli trailer Having Tire puncher Problem	3		All need repair/ replacement	3	Replacement of bearings and U-bolts	3		The Ace planter is good and usable; Changli very long can't be used due to road access.	3	
21	Masokotwani	2		Good, Changli Trailer Replacement Of bearing	3		All need repair/ replacement	3	Replacement of bearings and U-bolts	3		The Ace planter is good and usable; Changli very long can't be used due to road access.	3	
22	Kabbe	2		Good Changli trailer need Bearing	2		All need repair/ replacement	2	Replacement of bearings and U-bolts	2		The Ace planter is good and	2	

c) GRN Vehicle mounted sprayers and mist blowers repair and spare parts for 2026/27, 2027/28 and 2028/29

DESCRIPTION	QUANTITY	SERIAL NUMBERS	SERVICES/SPARE PARTS NEEDED
1. Vehicle mounted spraying machines (Q – 13 HP/15 HP)	7	419130593, 410767008 415439877 SR 21/1808	• Carburettor servicing and/or replacement • Spark plug replacements • Pump Blockage • Replacement of restrictors • Carburettor cable replacements • 15W40 oil replacement • Air filter replacements
2. Mist blowers (Solo type)	4	SR 450, SR 420	• Spark plug replacements • Carburettor servicing and/or replacement • Suction pipe replacements • Air filter replacements
3. Mist blowers (STIHL type)	6	SN1000217 SN 0005211 SN0005213 SN0005194	• Spark plug replacements • Carburettor servicing and/or replacement • Suction pipe replacements • Air filter replacements

d) GRN Walking Tractors and its Implements for MAFWLR- DAPEES Zambezi Region

ADC/ Location	ID of Tractor Make Chassis /Engine No.	Last recorded Service provided (Hours)	Last Date of service	Services Needed / Description of Problems (repair and maintenance)
Bukalo ADC	CHANG TUO CHANG	After 100 Hours service	Not Done since delivery and handover to DAPEES- Zambezi	• Routine service needed; • Mixing of oil & water
Chinchimani ADC	CHANG TUO CHANG	After 100 Hours service		• Routine service needed;
Sibbinda ADC	CHANG TUO CHANG	After 100 Hours service		Mixing of oil & water
Ngoma ADC	CHANG TUO CHANG	After 100 Hours service		• Routine service needed;
Masokotwani ADC	CHANG TUO CHANG	After 100 Hours service		Mixing of oil & water
Katima ADC	CHANG TUO CHANG	After 100 Hours service		• Routine service needed;
Linyanti ADC	CHANG TUO CHANG	After 100 Hours service		Mixing of oil & water
Sangwali ADC	CHANG TUO CHANG	After 100 Hours service		• Routine service needed;

Kongola ADC	CHANG TUO CHANG	After 100 Hours service		Mixing of oil & water
Sachona ADC	CHANG TUO CHANG	After 100 Hours service		• Routine service needed;
Kasheshe ADC	CHANG TUO CHANG	After 100 Hours service		Mixing of oil & water
Kabbe ADC	CHANG TUO CHANG			• Routine service needed;